

From: [Moore, Gary](#)
To: [Roberts, Lou](#)
Subject: RE: Frank J. Doyle Transformer Site
Date: Thursday, August 10, 2017 5:43:34 PM

Lou:

Thanks, I did not remember following up on this to get information.

It was just assigned to me to look at for additional investigation and possibly cleanup. It would appear that a cleanup is warranted based upon the levels that I am seeing but will have to do a more thorough investigation to determine extent of contamination and cleanup costs.

Thanks
Gary Moore

From: Roberts, Lou
Sent: Thursday, August 10, 2017 4:57 PM
To: Moore, Gary <Moore.Gary@epa.gov>
Subject: RE: Frank J. Doyle Transformer Site

Just Forwarded you 2 emails from back in 2015

Lou Roberts (6EN-H3)
Waste Compliance III Section
Waste Enforcement Branch
Compliance Assurance and
Enforcement Division
US EPA Region 6
1445 Ross Avenue, Suite 1200
Dallas, TX 75202-2733
(214) 665-7579
Fax (214) 665-7446

"This email may contain material that is confidential, privileged and/or attorney work product and is for the sole use of the intended recipient. Any review, reliance or distribution by others or forwarding without express permission is strictly prohibited. If you are not the intended recipient, please contact the sender and delete all copies."

From: Moore, Gary
Sent: Thursday, August 10, 2017 4:51 PM
To: Roberts, Lou <Roberts.Lou@epa.gov>
Subject: RE: Frank J. Doyle Transformer Site

Lou:

I don't remember us talking about this site previously. Do you have a copy of the email?

Thanks

Gary Moore

From: Roberts, Lou

Sent: Monday, August 07, 2017 10:24 AM

To: Moore, Gary <Moore.Gary@epa.gov>; Ehrhart, Richard <ehrhart.richard@epa.gov>; Sales, James <sales.james@epa.gov>

Subject: RE: Frank J. Doyle Transformer Site

Gary,

There was an enforcement action done in 1984 (Docket # TSCA 06-1984-0087). Looks like a penalty of \$50 paid. You would need to check out the TSCA Enf File or the Regional Hearing Clerk File for more information. You can send email to R6 Records Center and request TSCA Files.

You and I exchanged emails about this site back on 3/12/2015. Jim Sales had interaction with TCEQ in August 2016 (TCEQ contact: Eleanor Wehner, 512-239-6542; Eleanor.Wehner@tceq.texas.gov)

Hope this helps.

Lou Roberts (6EN-H3)
Waste Compliance III Section
Waste Enforcement Branch
Compliance Assurance and
Enforcement Division
US EPA Region 6
1445 Ross Avenue, Suite 1200
Dallas, TX 75202-2733
(214) 665-7579
Fax (214) 665-7446

"This email may contain material that is confidential, privileged and/or attorney work product and is for the sole use of the intended recipient. Any review, reliance or distribution by others or forwarding without express permission is strictly prohibited. If you are not the intended recipient, please contact the sender and delete all copies."

From: Moore, Gary

Sent: Monday, August 07, 2017 7:59 AM

To: Ehrhart, Richard <ehrhart.richard@epa.gov>; Roberts, Lou <Roberts.Lou@epa.gov>; Sales, James <sales.james@epa.gov>

Subject: Frank J. Doyle Transformer Site

All:

What do you know about this site?

I am looking for enforcement history. The removal program did removal assessments in 1991 and 1995. It showed elevated PCB contamination on and off-site but the facility was still in operations at the time and it appears that the assessments were done in coordination with TSCA. Wanted to find out if anything happened from an enforcement activity.

Thanks

Gary W. Moore (6SF-ER)
Federal On-Scene Coordinator
U.S EPA Region 6
1445 Ross Ave, Suite 1200
Dallas, TX 75202-2733
Cell: 214.789.1627
moore.gary@epa.gov